

WDR-3 Instructions

Caution: You will be working with a gentle but effective acid. **Eye protection is essential.** Rubber gloves are optional unless you have sensitive skin.

Contents:

- Descaling agent (3 pre-portioned packs)
- Red color indicator (3 pre-portioned bottles)
- Instructions & MSDS sheets

Step 1: Empty contents of one pack, dry descaling agent and red liquid indicator, into minimum 2 gallon bucket.

Step 2: Add one gallon of hot water at about 140°F and mix solution until completely dissolved.

Step 3: Circulate mixed descaling agent through appliance using a pump. Or soak parts in descaling agent.


Step 4: Allow circulation or soaking to continue for 15 minutes or longer as necessary. Solution is red when it is potent. A blueish-grey color means the solution has lost its acidity.

Step 5: When finished, dispose of descaling agent according to manufacturer's instructions or as local codes permit.

Step 6: Clean all parts with fresh water thoroughly. Change fresh water frequently to ensure descaling agent has been rinsed away.

Keep away from pets & children as acid is extremely dangerous.
Store descaling agent for future use in a safe space.
If you have questions contact: 800.605.6542.

Example: Descaling gas tankless water heater



Also available: WDKIT-4

Complete descaling kit Includes - bucket, pump, hoses, fittings and descaling agent